

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

EL'S NAME

"MALINI".

Rpt. Bgk.

No. 1263.

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

e of Survey


~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

Continuous Survey advanced.

Grounding damage:- Minor repairs effected to propeller fastenings.

It is submitted the vessel is eligible to remain as classed and WILL BE eligible for the record ~~ELMC~~ CS and date when the survey has been completed.

To complete the survey:- See Form 7E.



28.2.39.

The reasons for the renewal of  
No 2 auxy engine crank shaft  
should be stated

re Bgk: 3/3/39



© 2020

Lloyd's Register  
Foundation

W458-0037