

by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

SHIP'S NAME STEEL S.S. "GOLCONDA"

Hpl. 15673
Rpt. Sld. No. 27613

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey _____

First Entry.

The Surveyors should be requested to state whether the width of Upper
stringer plate is as shown on plans as built, or as given in report, whether
Bulkheads are plated vertically or if no whether ~~the~~ thickness of plating is
approved, They should state the thickness of keel at ends, and if the widths
strikes A, B & C are as given in report whether the riveting of butts ^{in A, B, C & E ends} is as approved,
whether the riveting of Bridge side ^{quintuple} butts is, as approved. It should also be stated
the rivets in the treble riveted shell butts are spaced 3½ diameters as required by
rules.

The usual Ship Fittings & Castings Report should also be forwarded

26.9.19.

W458-0143



© 2020

Lloyd's Register
Foundation