

d by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

EL'S NAME "BRIGHTON"

Rpt. _____ Gms. _____ No. 21198

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The Grimsby Surveyors report the vessel afloat and on account of damage whilst loading and discharging cargo, a sounding pipe has been repaired and minor repairs carried out.

The Surveyors recommend some further minor damages to ceiling, brackets in holds, hatchways and fittings, stanchions etc., which do not affect the vessel's efficiency, be dealt with at the Owners' convenience.

It is submitted the vessel appears worthy to remain as classed without record of survey, subject as recommended.

As now, subject etc.



Lloyd's Register
Foundation

W459-0139

W459-0138