

Total  
Gross Tonnage  
Register Tonnage

F.E.


2.15.

Received by Chief Ship Surveyor \_\_\_\_\_ Received from Chief Ship Surveyor \_\_\_\_\_  
VESSEL'S NAME SHS FARNDALE Rpt. SLD No. 29883

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

<sup>1st</sup> Transverse No. 12758 Depth "d" 23.4  
Description Butt angle frames as approved  
Framing: Table No. \_\_\_\_\_  
<sup>2nd</sup> Longitudinal No. 31408  
Proportions Length = 10.41  
Depth = \_\_\_\_\_  
Deck Sheerstrake as approved  
Revised Rules



This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✠ 100 A.1. (Steel) "with freeboard," as recommended. The Summer freeboard of 3<sup>ft</sup> - 3<sup>in</sup> from centre of disc to top of statutory deck line at \_\_\_\_\_ deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

1 D" (Stl) Shelter D" (Stl)  
Cell D.B 315' 9945, F.P.T. 1250, A.P.T. 2470  
F.K, 6 B.H (Collision B.H to Shelter D" 5 B.H to 2<sup>nd</sup> D" Cell)  
F 35'



W462-0117

DOUBLE BO  
Solid Floors