

COPY.

DLT
COX
CARE REGISTER
KOBE.

(24-8-36)

NORA MAERSK SEVERELY DAMAGED FIRE ENGINE ROOM WHILST ZAMBOANGA STOP
AT OWNERS REQUEST PICKERING PROCEEDED PHILIPPINES DEAL REPAIRS STOP
PICKERING HAS RETURNED HAVING ARRANGED TOWING HONG KONG VIA MANILA
STOP DAMAGE HULL EXTENSIVE MACHINERY GREATLY AFFECTED OWNERS NOW
DESIRE ENGINEER WIDEST EXPERIENCE KNOWLEDGE DIESEL ENGINES TO ADVISE
RESPECTING REPAIRS OR RENEWALS STOP CONSIDER YOUR PERSONAL
ATTENTION REQUIRED HULL AND APPOINTMENT MOST EXPERIENCED ENGINEER
DIESEL ENGINES JOIN MACDONALD ~~STOP~~ LEFT YOUR HANDS ^{stop} MAKE NECESSARY
ARRANGEMENTS PROCEED HONG KONG ACCORDINGLY OWNERS HAVE AGREED

COMMITTEE.

© 2020



Lloyd's Register
Foundation

W464-0124 1/2