

Cop


NORA MAERSK SEVERELY DAMAGED FIRE ENGINE ROOM WHILST
^{stop}
~~Z~~AMBOANGA AT OWNER'S REQUEST PICKERING PROCEEDED PHILIPPINES
DEAL REPAIRS STOP PICKERING HAS RETURNED HAVING ARRANGED
TOWING HONG KONG VIA MANILA STOP DAMAGE HULL EXTENSIVE
MACHINERY GREATLY AFFECTED OWNERS NOW DESIRE ENGINEER
WIDEST EXPERIENCE KNOWLEDGE DIESEL ENGINES TO ADVISE
RESPECTING REPAIRS OR RENEWALS STOP CONSIDER YOUR PERSONAL
ATTENTION REQUIRED ^d HULL AND APPOINTMENT MOST EXPERIENCED
ENGINEER DIESEL ENGINES JOIN MACDONALD ~~stop~~ LEFT YOUR HANDS ^{stop}
MAKE NECESSARY ARRANGEMENTS PROCEED HONG KONG ACCORDINGLY.

Owners have agreed

Jay

*Code 1/8
DP 1/4 1/2 Rev
250 22/11 add 11*

W464-0125



© 2020

Lloyd's Register
Foundation