

The 3rd S.S. No 3 ~~became~~ due 12.35 to be held within the year of grace - agreed to.

Chief Surveyors 20. 8. 36

Received from Chief Surveyors

SHIP'S NAME

SH. S. CAIRNGORM

Report

Gls

No.

57375

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

of Survey

Condition

When due

Vessel laid up.

Corroded bottom rivets in A+B strakes (prs) forward to be renewed to the 3rd S.S. No 3 to be held before the end of Dec^r 1936.

S.P.L.:- Insert corroded rivets

W.H.B.
21. 8. 36

Note:-

The vessel is now laid up as the Owners have not decided what they intend to do with her.

© 2019

Lloyd's Register
Foundation

W465-0070