

Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

EL'S NAME

*Caingon*

Report

*gls*

No.

*57325*

For the ~~CHIEF SHIP SURVEYOR~~ and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - (Extract from Sub-Committee's Report, 24/5/92.)

of Survey


*Docking*

When due

*Subject to screw shaft being examined, stern bush  
rewooded & shafting re-aligned & to funnel  
being repaired before vessel proceeds to sea  
Vessel is laid up indefinitely*

*Noted*

*Jun 22. 8.26*



Lloyd's Register  
Foundation

W465-0073