

of Survey

insured now in Markbykes

It is submitted that before this case comes consideration the Liverpool Mayor be requested to state whether he can confirm that the seven shafts examined by the S.C. Rimmer at Fleetwood in 1931 were found to be in good condition.

G. J. P.

28/8/32.



Lloyd's Register
Foundation

WH65-0241

100A1 (Steel) Steam Trawler.

1 Dk.

BK 7½, 3 BH. Cem.