

m.v. "FAYAL"

IT IS SUBMITTED the Lisbon Surveyor be informed
that the proposal to fit a taper brush in the propeller to
make it suitable for the ^{screw} new shaft is not considered
satisfactory.

[Signature] *VR*

3.7.1934.



© 2020

Lloyd's Register
Foundation

W466-0068 (114)

1.1.0