

"FAYAL"

It should be pointed out to the Surveyor that to enable the figure "1" to be assigned the equipment would require to be equivalent to the requirements of the Rules, which require 3 bower anchors to be fitted.


BOWER

It is noted that a 3rd anchor is on board, but that the marks are illegible and no certificate is available.

The Surveyor should be requested to discuss the matter with the Owners and to state whether the 3rd anchor referred to is of sufficient weight, and if so, whether the testing of same could be arranged, or alternatively whether the Owners would prefer to supply a 3rd bower anchor of suitable weight and test.

The weight of the ^{new} 3rd stockless bower anchor, if supplied, would require to be 10 cwt.

[Handwritten signatures and initials]
20.4.34



© 2020

Lloyd's Register
Foundation

W466-0088

Booms, thickness and spacing

Are Frame and Reversed Frame
logged?

Bridge Deck, Angle, [or [.....