

COPY.

SPT. RPT. N° 338

Lloyd's Register of Shipping.



Port

13th. December. 1934.

This is to Certify that I have

at the request of Messrs D. Tripacovich & Co., Trieste, who are stated to have bought the vessel,

Surveyed the ^{Main} Boiler and Machinery of the Steel screw steamer

"GEORGOS", 2040 Gross Tons, (No. 76701 in Register Book),

whilst under steam at the shipyard Brodogradilista Split A.D.,
Split, on the 13th. December, 1934.

and that I have transmitted to the Committee of Lloyd's Register

of Shipping, London, a Report, as on the other side, stating

~~that all repairs recommended by me have been completed to~~

~~my satisfaction~~, and that, in my opinion, the machinery is in
satisfactory condition for the duration of the voyage from
Split to Venice where, it is stated, the vessel is to be
broken up.

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."

295 Rpt. No 338

COPY.

Lloyd's Register of Shipping

Port of SPLIT.

17th December, 1934.



17th December, 1934.

"GENERAL EXAMINATION"

Main Boilers with mountings, doors and fastenings examined externally whilst under steam and found satisfactory. Safety valves tested and found in good working order. Main engine tested under steam and found satisfactory. All auxiliary pumps tested under working conditions and found efficient. Pumping arrangements examined and tested under working conditions.

Split, on the 17th December, 1934.

Engineer Surveyor to Lloyd's Register.

and that I have transmitted to the Committee of Lloyd's Register

Fee Din.1740

Expenses 161 London, a Report, as on the other side

Din.1903

~~that all repairs recommended by me have been completed to~~

~~and that, in my opinion, the machinery is in~~


~~satisfactory condition for the duration of the voyage from~~

~~Split to Venice where, it is stated, the vessel is to be~~

broken up.

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committee are their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of the Surveyors or other Officers or Agents of the Society."



© 2020

Lloyd's Register Foundation

Committee