

6E

23 OCT 1934

ved by Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

SEL'S NAME *Georgos*

Rpt. *Susak* No. *600*

emarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/32.)

ure of Survey _____

DAMAGE TO ENGINES AND BOILERS.

This vessel is reported by the *Susak* Surveyor to have sustained damage to *machinery & boilers* through *grounding*. ~~Temporary repairs have been effected to his satisfaction to enable her to proceed on her voyage to~~ *Venezuela* ~~now laid up.~~

The Surveyor recommends *ballast pump and general service pump* be repaired, *the boilers cleaned & examined,* *the piping arrangements dealt with in view of damage and the machinery cleaned out & examined.*

It is submitted *action be deferred.*

L.L.
23/10/34.



© 2020

Lloyd's Register Foundation