

of the tanks examined. Also state the amount of deterioration of the girders, and of the inner bottom plating, especially in the boiler space.

Last Report No.

18137 Port

OK

100 A. 1.
N. 100 A. 1.
3th 7
nd No. 3

board (if
ship and
whom?

and
C

Items:

Copp
Boat
Mas
Cond
Sail
Equ
An
Ch
Cal
Ha
St

essel i
rem

COPY.

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C. 3

2nd September, 1935.

Dear Sir,

R.

I duly received your letter of the 28th ultimo respecting the Steam Trawler "GARELOCH" which stranded at Billowness, Fifeshire, on the 18th of last month, and note your remarks to the effect that salvage operations will be attempted in the near future.

I regret that your reference to a Salvage and Repair Catalogue is not clearly understood, and, in the circumstances, I would suggest that you should apply to the Scottish Insurance Co. (Aberdeen) Ltd., regarding the matter.

I am, Dear Sir,

Yours faithfully,

Secretary.

William Gove, Esq.,
127, Balnagask Road,
Torry,
ABERDEEN.



© 2020

Lloyd's Register
Foundation

W466-0138

Survey 8. 35.