

10 MAY 1938

Chief Ship Surveyor 8.5.34

Received from Chief Ship Surveyor

NAME Stt. Sc. "BOMARSUND" Rpt. Ant. No. 19366

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.

DAMAGE.

This vessel is reported by the Antwerp Surveyor S  
have sustained damage to port & starboard bow plating through collision  
framing &c.


~~Temporary repairs have been effected to his satisfaction~~  
stated that the vessel is now indefinitely laid up  
~~on to enable her to proceed on her voyage to~~

The Surveyors recommend repairs be effected before the vessel is  
again placed in commission

It is submitted action be deferred for repairs

9.5.34

S.R.L. Repairs etc.



© 2020

Lloyd's Register  
Foundation