

2E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

"RAGNI".

Rpt.

Osl.

No.

4946.

...ks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey ~~COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No.~~

This Survey, due 2,37

partly held at

now

completed, and the following repairs carried out (due to wear and tear):-

The furnaces faired and re-inforced with stiffening rings.

2 combustion chamber backs partly renewed.

All tubes renewed.

Alterations.

Electrical installation has been fitted in accordance with the approved plans.

It is submitted the vessel is eligible to remain as classed, with notation of BS 6,37. as recommended.

15.7.37.



© 2020

Lloyd's Register
Foundation

W467-0275

Fullin...

RETAIN

It is submitted the vessel is eligible to remain as classed, with
as recommended.

18.11.77.



© 2020

Lloyd's Register
Foundation