

5-JUL-1921

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S.S. "ROSINA". Rpt. Pir. No. 1992

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

The class of this vessel is subject to indented plating on each side forward being dealt with.

The Piraeus Surveyor now reports the vessel examined in dry dock, the requirements of the 2nd.S.S.No.1, due 5.20, partly carried out, and the following repairs effected due to wear and tear:- 2 tank top plates in stokehold, 4 floors and several intercostals doubled, tunnel repaired and minor repairs. 4 indented shell plates have been renewed, and 3 repaired and in the Surveyor's opinion the shell plating is now in good condition with the exception of 2 plates on port side forward which, although efficient for the time being, are somewhat wasted.

The cables have been ranged and found correct as to length, but the diameter was not taken owing to the cables not being cleaned and a number of studs are missing.

The Surveyor states the vessel has been commandeered by the Greek Government and time did not allow of the cables being cleaned and repaired or the two shell plates being dealt with. The Owners state these will receive attention on the vessel's return to the U.K. when released from Government Service.

It is submitted the vessel might be allowed to remain as classed, with record of survey 6.21 and notation of S.S.Pir.No.1-21, subject to the chain cables being ranged, examined and dealt with as found necessary and to two shell plates on port side forward being renewed, as recommended.

100 A1  
6.21 Pir  
SS Pir No 1-21

} Subject to

2. 7. 21.

3468-0228