

Rpt. 12.

FREEBOARD VERIFICATION FORM FOR STEAMERS.

(When received in London Office)

Port

Vessel's Name

Cabo Bullera

Official No.

No. in Reg. Book

Port of Registry (For Foreign Vessels)

Seville

Material or Steel

Iron

State whether Classed by Lloyd's Register

100 A.1. Awaiting Dk

Name of Owners

Date of Verification

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned to the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line	ft.	ins.
From centre of disc to top of statutory deck line } at awning or part awning deck ! . . . }	<i>9</i> ft.	<i>8½</i> ins.
Fresh water line above centre of disc . . .		<i>5</i> ins.
Indian Summer line above centre of disc . . .		<i>✓</i> ins.
Winter line below centre of disc		<i>3½</i> ins.
Winter North Atlantic line below centre of disc		<i>✓</i> ins.
Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of wood or iron deck with the vessel's side	at main, spar or upper dk.	ins.
	at awning or pt. awning dk.	<i>1½</i> ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

3 certis Bbs

1 cert for B.T

22.4.19

Surveyor.

(To be filled up in London Office.)

Statement No.

Date of Committee's Minute

Moulded Depth for record

ft.

ins.

Freeboards compared and found correct by

date

Is fee paid?

Form for Certificate

A

Instructions

date

Certificate written

22.4.19

Noted for posting

Ima. 3, 15.—T.

W 469 - 0352

© 2019

Lloyd's Register Foundation