

Is Certificate required? If so, to be sent to

F.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

The Newcastle Surveyors have been notified.

P. 7.

ANCHORS.

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

Iron Stream Chain
or Steel Wire...

9a.
t of

dated

on the

Alterations :-

The space between frames 6 & 16; - engine room & after peak - converted into cargo hold, with W.T. flat fitted over shafting. A hatchway erected on deck over each hold.

Frames where cut in way of magazine fitted with back bars.

The W.T. door at aft. end of engine room is fitted with a manhole for access to intermediate shafting. This manhole is closed by means of a hinged & bolted door.

The whole of the above alterations have been carried out in accordance with the approved plans & Secretary's letters.

p. 7.

W470-0099(212)