

18th July, 1939

18

35.

Chief Surveyors

Received from Chief Surveyors

SHIP'S NAME Port Bowen

Report 91s

No. 60925

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

2nd S.S. No. 2 SURVEY PARTLY HELD.

due 6.39 When proposed to be ~~completed~~ ^{advanced} in London on return from present voyage.

of Survey held, &c., The greater part of the S.S. held.

To complete S.S. :- See Rpt.

Subject is indented and overlap of shell plates was 4 x 5 from forward in both strakes below shell in dk. sheenstrake (p.s.) being dealt with at owners convenience.

[Signature]
17.4.39

Dubb.

insert in R.B. E.S.D.



(E.S.D. filled 3.39)

© 2020

Lloyd's Register
Foundation

W470-0118