

W473-0059 1/2

COPY.

# Register of Shipping,

71, Fenchurch Street, E.C.3.

22nd July, 1936.

ance to the classification in the  
book of the Twin Screw Motorvessel  
inform you that the Society's Surveyors  
when this vessel was placed on the  
last it was understood that a  
was to be drawn up.

mention in their report that a  
plates were noted on both sides,  
stated to be leakage in a number of  
understood that since that time the  
as it would appear you had not  
should be undertaken of the vessel

, who have had the case under

glad to learn whether you have yet  
sion in the matter, and desire me to  
agree to the vessel's class remaining

ter Book in the meantime on the  
necessary repairs will be effected before  
mission.

will be glad if you will kindly favour

© 2019  
Lloyd's Register  
Foundation



COPY.

M.V. "PIONER".

- 2 -

them with a letter of assurance on this point.

I may add that it is understood that since the survey was held in March last, no repairs have been effected.

I am, Dear Sirs,

Yours faithfully,

Clerk to the  
Classification Committee.

Messrs. A. W. Nordstrom & Kr. Gjolberg,  
Ovre Slotsgate 27,  
OSLO,  
Norway.



© 2019

Lloyd's Register  
Foundation

W473-0059 72