

S. S. "PIONER"

Oslo 3593.

Before this case receives the consideration of the  
the Surveyors should be requested to state whether  
connections<sup>yes</sup> have been examined whilst the vessel was  
k, (and the pumping arrangements, fuel storage and daily  
anks have been examined<sup>no.</sup> at this time, and if not, what  
nts were made for these parts to be examined.

*See Oslo letter 1/5/31.*

*Km*

27.4.31.

*Lt to Os; 29/4/31*



© 2019

Lloyd's Register  
Foundation

W 473-0111



RETAIL



© 2019

Lloyd's Register  
Foundation