

11 - JAN 1934 2E

Inspected by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Pioneer

Rpt.

Blo.

No. *4207*

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/32.)

Title of Survey ~~COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No.~~

This Survey, due *3.34* ~~1st~~ ^{*now*} held ~~at~~

~~completed~~, and the following repairs carried out (due to *wear & tear*):-

*2 main cylinders renewed.
Minor repairs.*

RETAIN

It is submitted the vessel is eligible to remain as classed, with notation of *DA 12-33* *PS 12-33* as recommended.

DA

4/1/34



© 2019

Lloyd's Register Foundation

W473-0130

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.