

Received from Chief Ship Surveyor

by Chief Ship Surveyor

NAME Steel Aon M.S. "DANEDRONNING" Rpt. Ch. No. 6005

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

1st Entry

Before this case receives consideration the Surveyors should be requested to state whether the Collision bulkhead extends to upper deck or lower deck as stated in report; if the breadth given for edges of Bridge side plating is correct; weights of Stream & Kedge anchor staves, whether the 1st Bower anchor is a common or stockless anchor, if the former the weight of the stock should be given & if the latter they should state if it is of an approved type & whether the ballast tanks have been tested as required. It should be also pointed out to the Surveyors that the certificate numbers given for 2nd & 3rd Bower Anchors are the same.

Dr. 22/11/20

in letter to 11/11/20

M. A. S.
20-11-20
in letter 22/11



© 2019

Lloyd's Register
Foundation

W473-0173

[The following page contains faint bleed-through from the reverse side of the document.]