

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

7th July, 1936.

Dear Sirs,

M.

M.V. "JOSEPH MEDILL"

It is noted from Mr. Akester's First Entry Report on this vessel that four hatch beams were fitted to each hatchway, although the profile sketch of the vessel as built shews only three to be fitted, I have therefore to request that Mr. Akester will state which number is correct, and also give the scantlings as fitted.

He should also state what cleats and tarpaulins were provided, as there is no mention of these in his report.

As the matter is urgent a reply by return is desired.

I am, Dear Sirs,

Yours faithfully,

Secretary.

The Surveyors,

NEWCASTLE-ON-TYNE.



© 2019

Lloyd's Register
Foundation

W475-0084