

26 APR 1935

491

REPORT OF SURVEY for REPAIRS, &c.

of writing Report 3rd April 1935 When held at Local Office 19... Port of Bahia Blanca
 in Survey held at Bahia Blanca Date, First Survey 2 April Last Survey 1935
 Book. (No. of Visits one)

285 on the Wood, Iron or Steel S.S. "Oinoussios"
 TONNAGE: Built at Newcastle By whom Northumbria S.S. Co. Ltd. When 1904 12
 OSS 5804 Owners N. J. Pateras & Sons Owners' Address
 DER DK. 5549 (if not already recorded in Appendix to Register Book).
 T 3716 Managers Port belonging to Chios

Surveyed Afloat or in Dry Dock? Afloat Name of Dock Puerto Salvan Mole Destined Voyage London

B=Cell DBor DBa feet; uE&B feet; f feet
 Capacity tons. FPT tons; APT tons; MT feet tons.

All alterations in the existing records should be underlined.
 Fessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, of the inner bottom plating, especially in the boiler space.

Report, No. 15694 Port Port

Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; as being detailed in the body of the report, should be summarised in the form shown below. Whenever the extent of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on this form. State also the dates and initials of any letters respecting this case.

Cases where the Surveyor has not made a special damage report he is required to state whether he has services for this purpose and to whom and why they were declined.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned Survey expired.	Machinery and Boiler Surveys (including date of N.B. if any).
+100 A. 1.		+L.M.C.
10-33 9.34		B.S. 12.33
S.S. 24.2.11-3.31		M.S. 6.31
		C.L. 9.34

Society's Freeboard (if assigned) as painted on Ship and now verified ft. tons.

Was a damage report made by anyone else? If so, by whom?

OR EXAMINATION AS PER RULE, FOR

needed for permanent repairs to steel plate bracket carrying port side steering chain guide as per copy of report herewith enclosed.

OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
ed								
ed and Paired or Repaired								
or Repaired in place								

CONDITION OF THE

State if Tanks have been examined inside	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt). When put on, Month Year
State if Tanks now tested	Engine Room Skylights	Boats
Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Ceiling	Scuppers	Condition, how ascertained (State if wedges removed)
Cement or Asphalt (State which.)	Cargo Hatchways	Sails
Rudder	Hatches	Equipment letter
Steering gear and its connections	Planing of Wood Vessels	Anchors, No. of
Windlass	Caulking ditto	Cables (State if now ranged)
Have Pumps now been examined and found efficient?	Treenails ditto	length size (on board)
Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	Rule length size
Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Hawser & Warps
Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	Standing and Running Rigging
Plating	Ditto ditto at other places ditto	
	Stringers, Clamps & Shells ditto	
	Salting ditto	
	(State if examined.)	

al Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.24," or "to remain as classed and to have record of survey, 1.24, and the notations of ss No. 1-24 and ptND24, &c."

This vessel to continue as classed in the Register Book without further record of survey.

Survey Fee (per Section 29)	£	Fees applied for,	2 4 1935
Special Damage or Repair Fee (if any) (per Sec. 29)	£	Received by me.	2 4 1935
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

Committee's Minute

FRI. 10 MAY 1935

TUE. 3 DEC 1935

Character Assigned

as now subject
B.S. 135 subject

Work done

L.D. 1935

Surveyor to Lloyd's Register of Shipping.



© 2019

Lloyd's Register
Foundation

W476-0079