

(3m,6,4.)

Received by Chief Ship Surveyor 22.12.04

Received from Chief Ship Surveyor _____

VESSEL'S NAME St. L. Filippo Artelli Report Nwc. No. 48051.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey 1st entry.

It is submitted that before this case receives the consideration of the Committee the report ^{together with sketch of midship section and profile} should be returned to the Surveyors, and they should be requested to indicate thereon the thickness of the upper deck stringer plate, and topside plating in the midship half length of the vessel beyond the ends of the bridge, as the thicknesses shown on their report relate to thicknesses in way of bridge.

Mr. Hwc 22/12/04

L. H. T.
22/12/04

C. J.



© 2019

Lloyd's Register
Foundation

W476-0088

Quarter 'tween Dks.,
in Hold

...leaving from dynamo main switch board
...and how protected 3/4" 1-
...stores, or baggage
...one be