

1m, 12, 20.

BOARD REPORT on the

S.S. "Simon Bolivar"

It is submitted the Surveyors be informed that it is observed that a number of openings are fitted in the vessel's sides forward between the upper and second decks, and that these openings are closed with portable wood shutters only. The case will therefore fall to be dealt with as a well deck vessel and the Surveyors should forward an amended report on form 116 giving the depth and all particulars regarding sheer and erections on the second deck. They should also give full particulars of freeing ports and scuttles from all spaces on this deck.

W.B.

11. 3. 27 © 2019



Name of Broker or Agent

vessel is lying at *Rotterdamsche Droogdok Maatschappij, Rotterdam.*

ler Book

W 478-0043

Lloyd's Register
Foundation

12-03/2