

COPY.

Hamburg Report Nr. 21124

Lloyd's Register of Shipping.



Port of H A M B U R G .

16th of April 1934.

This is to Certify that

xxxxx Fr. Ohlzen, xxxxx

the undersigned Surveyor to this Society did at the request of the Owners Representative survey afloat and in dry dock at Hamburg the Steel Co." SIMON BOLIVAR " 7906 tons gross of Amsterdam for damage alleged sustained through heavy weather during the voyage from Funchal to Plymouth on the 31st of March 1934.

For full particulars see entries in vessel's Log Book.

On examination of the vessel in dry dock at Hamburg on the 10th of April 1934 and subsequent dates, the undersigned found the following damage and made the accompanying recommendations:

FOUND:

The Rudder badly strained.

On starb.side in way of oil fuel bunkers 6 and on port side 8 shell rivets slightly leaking.

In way of after peak on port & starb.side a number of rivets & seams of the shell plating also the scarp of propeller post started.

Small leakages through the decks in way of luggage room and cabins Nos. 29, 61, 65, 94 and 3rd. Class dining saloon.

RECOMMENDED:

The Rudder to be lifted for examination, neck bearing of the Rudder shaft to be removed and rebushed and the gland to be re-packed.
Leaky shell rivets to be recaulked.

Started rivets & seams to be recaulked & rep. by electr. welding.
Bolts in scarp of propeller post to be renewed.

Leakages to be tightened as necessary and wooden decks in way of to be recaulked.

It was further recommended, that all disturbed work in way of the damage be made good or be replaced and the repairs be tested and recoated on completion of the repairs.

Fee: £ 5 : 0 : 0 .

(Five Pounds)

incl. expenses.

Friedrich Ohlzen.

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Committee or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."