

12 JUN 1931

Received by Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

VESSEL'S NAME Steel Sc. "DUNAFRIC" Rpt. Bel. No. 10627

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32).

Nature of Survey .....

The class is subject to indented shell plate H2 on port side being dealt with at the Owners' convenience.

The Belfast Surveyors now report the vessel placed in dry dock and the requirements of 2nd S.S. No.1, due 4.31, complied with.

The bottom has been cleaned and coated and repairs effected to shell plating, frames, floors, windlass and minor repairs carried out


It is submitted the vessel appears worthy to remain as classed with record of survey 5.31 and notation of S.S. No.1-31, without special condition.

100A1  
Awning deck with freeboard ) without etc.  
5.31 Bel. )  
S.S. Bel. No.1-31 )

X

PLATING to be DRILLED when vessel is 24 years old, or at next Special Survey thereafter.

X



  
11.6.31.



© 2019

Lloyd's Register  
Foundation  
W 479-0167