

s/c "Vennachar".

Erk. Apt 16986

It is submitted, that the Greenock Surveyors should be informed, it is concluded they are not correct in reporting that the screw stays fitted to the main boilers are steel, as in the approved plan they are shown as iron, but they should state whether this is so.

JWZ.

11/4/16

© 2019

Lloyd's Register  
Foundation

W 479-0192