

Surveyor

Received from Chief Engineer, Surveyor

Joseric.

Rpt.

Npt.

No.

235-61.

Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points of the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

~~PAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

PS due 1-36, 2nd SSN due 2-35.

Boiler furnaces examined.
The surveyor recommends the removal of the Centre furnace of the Centre Boiler & the port & Centre furnaces of the Starboard Boilers.

These repairs will be effected & the Special Survey held before the vessel sails.

Submitted action be deferred.

27/1/36.

complete the turbine
key for the vessel & the 1-35
thrust & intermediate
to, condensers, and pumps,
piping arrangements,
electrical equipment &
in pipes to be examined

27/1/36



© 2019

Lloyd's Register
Foundation

W479-0306