

Less  
Less  
Less

5c.12.16.

F.E.

Chief Ship Surveyor 12.8.18 Received from Chief Ship Surveyor \_\_\_\_\_

NAME Sheels "War Parrot" Rpt. SL No. 27303

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 83 Depth "d" 18.4

Table No. 3 page 15 Description Bull angle as approved

Longitudinal No. 33200

Proportions Length = 10.2  
Depth

Bridge Deck Sheerstrake as approved

Downer pump & keel anchor dispensed with as in Standard Vessels  
Large battens not fitted in tween Decks

This vessel appears to have been built in accordance with the plans and the approved plans, and it is submitted she is eligible to be classified \* 100A-1 (Steel) as recommended.

2 Decks (Steel)

Cell 5. B 340 .11346. F.P.T. 1246 A.P.T. 1956


F.H. 7 BH. pl. Cam. Leaper. P49 B 112' F 39'

Carrying oil fuel F.P. above 150°F in 5 Bottom.

Certificate of Classification, to be endorsed with the words "Large battens not fitted," and the same endorsement to be printed in the Register Book.

M  
12.8.18

It is suggested a second means of steering by retaining the tackle as has been provided as in the similar vessels, but the Surveyor should state if this is necessary.



F.E.

Received from Chief Ship Surveyor

No. 2320

Rdt.

of the Chief Ship Surveyor are desired on this case for the consideration of the Shipping Committee

The endorsement to be put on a vessel's register is subject to the condition that the vessel shall be found to comply with the provisions of the Act in all respects, and that the vessel shall be found to comply with the provisions of the Act in all respects, and that the vessel shall be found to comply with the provisions of the Act in all respects.

Verse No. 83

Depth "d"

Description

Proportions  
Depth

Length

REMAIN

This vessel appears to have been built in accordance with the and the approved plans, and it is submitted she is eligible to

100 A 1

One of the

20/19/15  
with pack  
No Ten



© 2019

Lloyd's Register  
Foundation

Less Crew Space  
Less above Crown  
Passage Room  
FOR FR  
Engine Room  
Investigation S  
er Tomm  
on Beam  
ETH on L  
er Rule  
isions of  
ME, Ang  
in peak  
in way  
"  
g of Fr  
ERSE  
in way  
"  
ING,  
RS, a  
a  
in wa  
thickn  
depth  
high  
RS in  
st  
Sp  
RE G  
Br  
GIR  
IN F  
B  
H  
B  
"  
"  
S, U  
S  
P