

Steamer "JIUL".

It is submitted Mr. Demarest should be requested by telegram to state the position of the buckled shell plates and floors, also whether he has seen this damage and, if so, what in his opinion is the cause. He should further give the same information regarding the damage to the rudder.

C.F.

25.7.17.



© 2020

Lloyd's Register
Foundation

W48-0055