

T.S.S. "Juna."

Nw. 81484.

It is concluded that 2 Spare bottom end bolts & nuts are placed on board. & that the bottom plates of the boiler combustion chambers are  $\frac{27}{32}$ " not  $\frac{23}{32}$ " as reported. It is submitted that the Surveyors should state if this is so.

See Mac ltr 29/6/27

W. H. 28/6/27

W48-0146

A REPORT ON MAIN BOILERS NOW FORWARDED? yes ✓