

S.S. "WORON".

Called and saw Mr. Howard Glover in regard to this case and he asked that a letter might be addressed from this Office to the Society's Surveyors at Newcastle requesting them to state the nature of the repairs effected to the H.P. Cylinder at the time of their survey of the engines of this vessel from May to July 1921.

*I am.*

27.2.22



© 2020

Lloyd's Register  
Foundation

W48-0159