

UNDERTAKING CASE

24 MAY 1934

Chief Surveyors 12 3 MAY 1934

Received from Chief Surveyors

L'S NAME Muzer "Graham Lynn" Report Krb. No. 578

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

of Survey 2nd S.S. No. 1 When due 3.29
2nd S.S. No. 2 due 3.33

As due 5.27.

The 2nd S.S.No.1 became due 3,29.


The 2nd S.S.No.2 became due 3,33.

The vessel being laid up the Owners have furnished the usual undertaking.

In December last the Karachi Surveyor reported the vessel placed in dry dock, bottom cleaned, found in good condition and coated.

The vessel is still laid up, and the year of grace for the 2nd S.S.No.2 expired at the end of March last.

The case is submitted for the consideration of the Committee.



[Handwritten signatures and initials]
 Lloyd's Register
 Foundation

W480-0016