

30 MAY 1939

1

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Pensilva

Rpt.

Cff

No.

52888

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

ature of Survey

DAMAGE.

Damage through contact with dock wall (See also Gls. Rpt. No 60290)
ranging o hatch beam dropping

now repaired as follows:-

	Shell Plates	Main Frames	R Frames	Floors & Bracket Floors	Inner Bottom Plates	Deck Plates	Beams
Renewed	3						
Removed and faired or repaired.....	3						
Faired or repaired in place.....					1		

Other items:- Vessel examined in dry-docks the bottom cleaned o coated o repairs effected to Stem, bulwarks, etc.

On account of wear o tear the shell plate in way of main discharge has been doubled o repairs effected to starting gear o ash shoot.

It is submitted the vessel is worthy to remain as classed with record of Survey 4.39 without special condition

100 A.1.
4.39 Cff / without, etc.



© 2020

Lloyd's Register
Foundation

W 48 00 44