


"Wheatsheaf."

Gls. Rpt. 35489.

It is submitted, that the Glasgow Surveyors should be  
ked to state whether the after end of the screw shaft  
ner is made watertight in the propeller box, the number  
size of the donkey boiler safety valves, pressure to which  
they are adjusted, if fitted with easing gear, if steam  
enter from the main to the donkey boiler & where  
the donkey is fitted, as these particulars are not  
given on the report.

7. 10. 15.

JRS



© 2020

Lloyd's Register  
Foundation

W 481-0150