

If the tanks examined. Also state the amount of the tanks examined. girders, and of the inner bottom plating, especially in the boiler space.

+100 A.L. 8.31
Shelter deck with freeboard

Last Report, No. 20192 Port Ham

5m,10,30.

FEB 1932

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S.S. "ELSA MENZELL" Rpt. Rot. No. 20880

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32).

Nature of Survey

The class is subject to the vessel being further examined in dry dock and permanent repairs being effected to the stern frame at the Owners' convenience and to the stem shoe, repaired by electric welding 8.31, being specially examined at the next dry docking.

The Rotterdam Surveyors now report the vessel placed in dry dock for examination after grounding, repairs effected to shell plates, beams etc., upper and lower parts of stern frame, rudder head and mainpiece and foundation plate of steering engine all renewed and minor repairs carried out.

A bower anchor and one length of chain cable previously lost have now been recovered and placed on board and this chain cable retested. Two ^{new} lengths of chain cable of proper size, weight and test have also been supplied.

The electric welding repair to the stem has been examined, found satisfactory and the Surveyors recommend the condition regarding same might be removed.

It is submitted the vessel appears worthy to remain as classed with record of survey 1.32, without special condition, as recommended.

100A1 Shelter deck with freeboard. } without etc.
1.32 Rot. }



Travelling Expenses (if chargeable) 10.00
Second Surveyor's Fee (if any) 12.50
Surveyor to Lloyd's Register