

COPY.

Hamburg Report Nr. 20047

Lloyd's Register of Shipping.



Port of H A M B U R G .

31st August, 1931.

This is to Certify that I have

surveyed the Boiler and Machinery of the Steel So. ELSA MENZELL,

tons gross of Hamburg afloat and in dry dock at Hamburg

damage and damage repairs, annual survey of boilers and

rotation of tail shaft when drawn ~~XXXXXXXXXXXXXXXXXXXXXXXXXXXX~~
that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report stating that all

recommendations made by me in connection therewith have

been carried out to my satisfaction, and that I have


recommended that the record of BS-8,31 and TS(CL)-seen 8,31

~~XX~~

made in the Register Book in the case of this vessel.

[Handwritten Signature]
Engineer Surveyor to Lloyd's Register.

is issued upon the terms of the Rules and Regulations of the Society, which provide that :—
The Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is
that neither the Committee nor the Society are under any circumstances whatever to be held responsible for
in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other
of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents



Lloyd's Register
Foundation
W481-0045