

TTTS, ENGINEERS."

ABERTAY WORKS,  
TAYPORT.


23rd April, 1925

D. & R. B. SCOTT,

MECHANICAL AND ELECTRICAL ENGINEERS,

MINE AND ENGINEERS' FURNISHERS.

Registry of Shipping,  
71, Fenchurch Street,  
L O N D O N E.C.3.



There are Six Babcock & Wilcox Boilers lying at Kinghorn which have never been installed in vessels.

When manufactured these were tested by your Surveyors dated 2/2/1921

6/1107 A  
6/1107 B  
6/1107 C  
6/1108 A  
6/1108 B  
6/1108 C

These have been lying in the open for some time and the some cases are rusted.

With a view to getting them sold we wrote your Leith Office, in their district, and asked if they could give a report and Mr. David Scott met their Surveyor at Kinghorn yesterday. Talking over the matter with his Chief they 'phoned us this day that before they could give a report on them water tests would be necessary. This, however, is quite out of the question and would mean their fitting together and entail expense.

We were negotiating their sale to South America, for land use, with a view of having an authoritative report on their present condition that we have approached your good selves.

They cannot be sold as new boilers, and your original report would not cover them after standing exposed in the open, I am writing you now.

We should be glad of your help and guidance in this matter and it would be a pity to see such good material lost.

Yours very truly,

D. & R. B. Scott

Lloyd's Register  
Foundation

W482-0106



Referred to the Chief Engineer Surveyor.

*as*  
24 APR 1925

*Spl*



© 2019

Lloyd's Register  
Foundation

SHIP AND ENGINEERS' FURNISHERS  
AND ELECTRICIAN'S FURNISHERS

B. SCOLL

SHIP AND ENGINEERS' FURNISHERS  
AND ELECTRICIAN'S FURNISHERS