

COPY.

XXXX

Lloyd's Register of Shipping

Jacksonville.

31st October, 1929.

71, Fenchurch Street, E.C. 3.

H

HIS All requirements of S.S. No.2 remain to be complied with except

examination of bottom and rudder

testing of d.b. tanks

testing of fore and after peak tanks

examination of winlass

the following remains to be done to complete S.S. No.2

as regards

machinery

valve chests

of

main

feed pump

require to be renewed

stop

centre main boiler safety valves

require to be adjusted

and

boilers

require to be repaired

as recommended by

you

July last

stop

you may

survey this vessel

again

if requested to do so

by

Master

or

agents

of

NEW YORK

stop

please refer to your report No.

fees are paid



© 2019

Lloyd's Register
Foundation

W482-0151