

Received from Chief Surveyors

Chief Surveyors

EL'S NAME *H. L. "ELSA MENZELL"* Report *Bal* No. *5132*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey *Examination afloat after* When due
collision.

*Subject to vessel being further examined
in dry dock & permanent repairs being effected to the
stern frame at the Owner's convenience & the stem shoe
repaired by electric welding being specially examined
at the next dry docking.*



© 2019

Att.

Lloyd's Register
Foundation

W482-0295