

S.S. "WASA HIKARI"

-2-

Cont'd.

REPAIR

RECOMMENDED

Shell plating in way of same  
to be hose tested, proven tight  
and repair coated.

Cost of effecting repairs with vessel lying at her  
discharging berth including barge hire, scaffolding and tools, etc.  
also necessitating the breasting of vessel from wharf, One Hundred  
and forty dollars (\$140.00).

*C. J. Vastu*

Surveyor to Lloyd's Register of Shipping



© 2019

Lloyd's Register  
Foundation

W482 - 0298