

Received from Chief Engineer Surveyor

of Engineer Surveyor

NAME S.S. "ELSA MENZELL"

Rpt. Boston

No. 2651.

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. (Extract from Sub-Committee's Report, 24/5/192.)

DAMAGE & WEAR AND TEAR.

The Boston Surveyor reports that the vessel has sustained damage through ice..

Machinery partly examined.

Repairs recommended. The Surveyor recommends these repairs to be carried out on arrival at New York from Hamburg

submitted the vessel is eligible to remain as classed without fresh of Survey as recommended., subject to repairs being effected New York and Hamburg.

in Hamburg Surveyors.



CB
© 2019
7. 4. 31.

Lloyd's Register
Foundation

W482 - 0826