

Subject to repairs being effected to ceiling, tunnel, pillars etc at Owner's first opportunity or convenience

8

21 JUNE 1927

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *St. Se. HCHDAIRNIE*Rpt. *CH*No. *46868*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey

DAMAGE.

This vessel is reported by the *Cardiff* Surveyors

to have sustained damage to *injection valve compartment* through *heavy weather*

Temporary repairs have been effected to *their* satisfaction to enable her to proceed on her voyage *to*

The Surveyors recommends that the riveting & caulking of the injection valve compartment be made good in drydock

It is submitted the vessel appears worthy to remain as classed without record of survey subject as recommended above.

As now; Subject &c.

W. H. M. A.
21. 6. 27



© 2019

Lloyd's Register
W482-0404
Foundation