

WIRE.

Steamer Inchdairnie returning your port with defects to
HP turbine thrust owner proposes to fit old turbine for
one Atlantic voyage without renewing rotor shaft. stop.
give case immediate attention and inform this office
whether in your opinion owners proposal is satisfactory.

11/11

J. L. W. G. H.

16.11.26.



© 2019

Lloyd's Register
Foundation

W482-01433