

Received by Chief Ship Surveyor 19.11.14.

Received from Chief Ship Surveyor

VESSEL'S NAME Stl.Sc.K. "HERCULES".Rpt. Hul.No. 28078

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report. 24/5/92.)

Nature of Survey

CONDITION.& fitting new Boilers

This vessel has been placed on a slipway, bottom cleaned and coated, two floor plates below boiler fitted with double reverse frames, all boiler stools renewed, 17 reverse frames in bunkers repaired, bunker casing repaired and minor repairs effected.

It is submitted the vessel appears worthy to remain as classed with fresh record of survey as recommended.

100 A.1Steam Trawler11.14Hul.W486-14
19.11.14

© 2019

Lloyd's Register
Foundation

W486-0020