

Surveyors 10/7/12

Received from Chief Surveyors

NAME At S Hera

Report Grk

No. 16285

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Survey First entry

When due

Subject to

+ 100 A.L. (2nd) "Carrying, petroleum in bulk",
2nd (etc) Web frames, "Longitudinal framing"


W/B. Cull DB u/b 78' 123' EPT 138' APT 90'

FK 10 BH. 15 BH to upper deck & 1 BH to 2nd deck, Lloyd's area
P 103' B 28' F 42.

Y.M.

R.M.
10/7/12.

Subject to the stern frame, which is reported to have
been damaged when the vessel was launched, being
repaired in 2 months time as proposed.



© 2019

Lloyd's Register
Foundation

W486-0074